



DEX GOOD, BETTER, BEST CODING FOR WEBSITE

GOOD

Item has notable signs of operational and cosmetic wear. Item is in functional condition.



8211 BONNET; COVER

Description:
VOLVO HOOD 20769889

Tag#: 483692

OEM#: 20769889

Category: Recycled

Condition: Good

Location: Advance, NC

Core Charge (per): \$0.00

Price (per): \$968.32

BETTER

Item has medium signs of operational and cosmetic wear.



8211 BONNET; COVER

Description:
VOLVO HOOD 78587454

Tag#: 485582

OEM#: 78587454

Category: Recycled

Condition: Better

Location: Advance, NC

Core Charge (per): \$0.00

Price (per): \$1,467.13

BEST

Item has minimal signs of operational and cosmetic wear.



8211 BONNET; COVER

Description:
'17 Volvo VNM complete groomed hood, with head lights, turn signals, grille, spot mirror, vent, etc... p/n 20769888, clean hood

Tag#: 643542

OEM#: 20769889

Category: Recycled

Condition: Best

Year: 2017

Make/Model: VOLVO

Location: Advance, NC

Core Charge (per): \$0.00

Price (per): \$1,627.08

For all conditions, be sure to refer to www.dexheavydutyparts.com for all images. Images will include multiple angles of the part and any wear and/or damage."

CHECKDEX

HOW TO VIEW INVENTORY

Visit www.dexheavydutyparts.com

1. Click in the search bar to expand

2. Choose applicable icon:
Renovated, Recycled, or Surplus

3. Select your additional filters and
click Find My Part

Locations: Oklahoma City, OK | Advance, NC

www.dexheavydutyparts.com | toll free **888-631-3409** | customerservice@dexheavydutyparts.com